

03500.017725.



cofe

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
FUMITAKA TOYOMURA, et al.)
Application No.: 10/717,641)
Filed: November 21, 2003)
For: PHOTOVOLTAIC POWER)
GENERATING APPARATUS,)
METHOD OF PRODUCING)
SAME AND PHOTOVOLTAIC)
POWER GENERATING SYSTEM)
U.S. Patent No.: 6,966,184)
Issued: November 22, 2005) August 3, 2006

*Certificate
AUG 08 2006
of Correction*

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

AUG 09 2006

No fee is believed due; however, any necessary fee should be charged to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Diamond E. Vadnais
Attorney for Patentees
Registration No. 52,310

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 117991v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,966,184

DATED : November 22, 2005

INVENTOR(S) : FUMITAKA TOYOMURA, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 45, Begin a new paragraph before "In".

COLUMN 2

Line 15, "solar," should read --solar--.

COLUMN 20

Line 14, "converter-2" should read --converter 2--.

COLUMN 23

Line 15, "material-used" should read --material used--.

COLUMN 24

Line 50, "systems," should read --system,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,966,184No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

117992 (Form#30)

→
AUG 09 2006

03500.017725.



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
FUMITAKA TOYOMURA, et al.) : Examiner: Hoang Nguyen
Application No.: 10/717,641) : Group Art Unit: 3748
Filed: November 21, 2003) :
For: PHOTOVOLTAIC POWER)
GENERATING APPARATUS,) :
METHOD OF PRODUCING)
SAME AND PHOTOVOLTAIC) :
POWER GENERATING SYSTEM) :
U.S. Patent No.: 6,966,184) :
Issued: November 22, 2005) : August 3, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULE 322

Sir:


It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

AUG 09 2006

No fee is believed due; however, any necessary fee should be charged to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Diamond E. Vadnais
Attorney for Patentees
Registration No. 52,310

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 117991v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only

PRINTER'S TRIM LINE

PATENT NO. : 6,966,184

DATED : November 22, 2005

INVENTOR(S) : FUMITAKA TOYOMURA, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 45, Begin a new paragraph before "In".

COLUMN 2

Line 15, "solar," should read --solar--.

COLUMN 20

Line 14, "converter-2" should read --converter 2--.

COLUMN 23

Line 15, "material-used" should read --material used--.

COLUMN 24

Line 50, "systems," should read --system,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,966,184

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
117992 (Form#30)

→ _____

11/20/2005